

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

FEB 24 2011

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	High Lonesome 26 Federal Com	Facility Type	Tank Battery

Surface Owner	Federal	Mineral Owner		Lease No.	NMMN-118710 (API#) 30-015-31899
---------------	---------	---------------	--	-----------	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	26	16S	29E					Eddy

Latitude 32 53.866 Longitude 104 02.455

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	17bbls	Volume Recovered	15bbls
Source of Release	Water tank	Date and Hour of Occurrence	02/10/2011	Date and Hour of Discovery	02/10/2011 5:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The water pump froze and the alarm system malfunctioned due to freezing temperatures. The water pump has thawed and returned into service and the alarm system malfunction has been repaired.

Describe Area Affected and Cleanup Action Taken.*

Initially 17bbls was released from the water tank at the facility and we were able to recover 15bbls with a vacuum truck. The release was completely contained inside the facility walls and the entire facility is lined with 40mil plastic. Contaminated gravel has been removed, tank has been steam cleaned, and fresh gravel will be added to the facility as necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name:

Josh Russo

Title:

HSE Coordinator

E-mail Address:

jrusso@conchoresources.com

Date:

02/22/2011

Phone:

432-212-2399

Approved by District Supervisor:

Approval Date: 3/2/2011

Expiration Date: N/A

Conditions of Approval: NA

Attached ☐

* Attach Additional Sheets If Necessary

2RP-621