

RECEIVED JAN 18 2010

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-24092

## Release Notification and Corrective Action

NMLB/10693/205

## OPERATOR

☒ Initial Report ☐ Final Report

Name of Company COG OPERATING LLC 229137	Contact Kanicia Carrillo
Address 550 W. Texas, Suite 100 Midland, TX 79701	Telephone No. 432-685-4332
Facility Name - Spruce Federal #1	Facility Type- Battery

Surface Owner Federal	Mineral Owner	Lease No. NM96836
-----------------------	---------------	-------------------

## LOCATION OF RELEASE

Unit Letter	Section 25	Township 17S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	------------	--------------	-----------	---------------	------------------	---------------	----------------	-------------

Latitude N32 48.145 Longitude W104 14.014

## NATURE OF RELEASE

Type of Release- Produced water	Volume of Release-50 bbls	Volume Recovered- 0
Source of Release- Heater treater	Date and Hour of Occurrence- 01/04/10	Date and Hour of Discovery 01/04/10
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher & Terry Gregston	
By Whom? Pat Ellis	Date and Hour 1/05/10 8:25am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The release occurred when a water leg on a heater treater separated.

Describe Area Affected and Cleanup Action Taken.\*

Spill traveled about 150 yards out in the pasture. Will await approval from the BLM to remove 2' of saturated soil in the pasture.  
Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION


Signature:



Printed Name: Kanicia Carrillo

Approved by District Supervisor

Signed By



Title: Regulatory Analyst

Approval Date: 3/10/2011

Expiration Date:

E-mail Address: kcarrillo@conchoresources.com

Conditions of Approval: Remediation per NMOCD Rules &amp; Guidelines

Attached ☐

Date: 01/12/10

Phone: 432-685-4332

\* Attach Additional Sheets If Necessary

Late entry - Release # 1 of 2  
2nd Release date 7/24/2010  
As of 3/10/2011 Remediation proposal to address both releases Approved

ZRP-429