


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brizos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Berry A Federal #1	Facility Type	Well

Surface Owner	Federal	Mineral Owner		Lease No.	054988
---------------	---------	---------------	--	-----------	--------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	21	17S	30E	330	NORTH	1650	WEST	Eddy

Latitude 32.82643 Longitude 103.980206

NATURE OF RELEASE

Type of Release	Produced fluid	Volume of Release	Volume Recovered
Source of Release	Casing	Date and Hour of Occurrence	Date and Hour of Discovery
		05-18-10	05-18-10
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
		Mike Bratcher-OCD	
		Terry Gregston-BLM	
By Whom?	Pat Ellis	Date and Hour	05/18/2010 4:15 p.m.
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The Berry A Federal #1 well had a casing leak while in the process of plugging and abandoning the well. A temporary pit around the well head area was immediately constructed to contain the water flow. The leak was stopped and the well has successfully plugged and abandoned.

Describe Area Affected and Cleanup Action Taken.*

Due to water flow during the plugging process, and additional 3600bbls of water was released and taken to a disposal under a controlled recovery condition. The saturated soil was removed and the release site will be sampled by Tetra Tech Environmental to determine appropriate clean-up actions and work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Patrick L. Ellis</u>	OIL CONSERVATION DIVISION	
Printed Name: Patrick Ellis	Signed By: <u>Mike Bratcher</u>	
Title: HSE Manager	Approved by District: <u>11</u>	Signed By: _____
E-mail Address: pellis@conchoresources.com	Approval Date: <u>3/23/11</u>	Expiration Date: _____
Date: 07/16/2010 Phone: 432-230-0077	Conditions of Approval:	
	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	
	<u>4/23/11</u>	

* Attach Additional Sheets If Necessary

Attached ☐

2 RP 651