

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-26931

Release Notification and Corrective Action

NKMW 1106629393

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P.	260737	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 432-556-8730
Facility Name: Golden 8 Federal Battery #1		Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No.
-----------------------	-----------------------	-----------

LOCATION OF RELEASE

Unit Letter K	Section 8	Township 21S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.491352 Longitude W 104.008223

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 310 Bbls Crude oil	Volume Recovered: 290
Source of Release: 500 bbl tank overflow	Date and Hour of Occurrence 2/16/11 hour not known	Date and Hour of Discovery 2/16/11 10:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency reporting. Left message with details.	
By Whom? Tony Savoie	Date and Hour 2/16/11 1:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A 500 bbl. Oil product tank overflowed due to a heater-treater malfunction. The heater-treater was repaired and put back in service.

Describe Area Affected and Cleanup Action Taken.* An area inside the earthen tank containment measuring approximately 14,100 sq. ft. and an area of pasture land outside the containment measuring approximately 400 sq. ft. The area outside the containment had been affected by a previous flow line spill reported to the NMOCD on 10/6/10. The oil saturated soil outside the containment was removed by Basin Env. using a hydro-vac. Approximately 290 bbls of crude oil was recovered from inside the containment. The area inside the containment was covered with soil to absorb small areas of free product. The Site remediation for the crude oil spill will follow the NMOCD guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor: Signed By: Mike Brannan	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: 3/7/11	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/3/11	Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 4/7/11	

* Attach Additional Sheets If Necessary

2RP-633