


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-27536

Release Notification and Corrective Action

TKMW 1035628897

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P.	260737	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 432-556-8730
Facility Name Poker Lake Unit #78 Delaware B Tank Battery		Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No.
-----------------------	-----------------------	-----------

LOCATION OF RELEASE

Unit Letter A	Section 25	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.194069 Longitude W 103.827614

NATURE OF RELEASE

Type of Release: Produced water.	Volume of Release: 90 Bbls of Produced water.	Volume Recovered: 80 bbls of produced water.
Source of Release: 500 bbl produced water tank.	Date and Hour of Occurrence Unkown	Date and Hour of Discovery 7/7/10 10:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy NMOCD on call operator	
By Whom? Tony Savoie	Date and Hour 7/7/10 2:39 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A pipe connection on the back of the water tank broke "reason unkown" The 2" valve between the tank and the pump was closed stopping the flow of water. The connection was replaced later.

Describe Area Affected and Cleanup Action Taken.*The released fluid affected an area of approximately 2,000 sq. ft inside the earthen containment around the tanks, the facility does not have impervious containment. The free standing fluids were removed with a vacuum truck. On 5/25/10 An area was selected inside the containment for an air rotary rig to advance a soil bore to determine vertical extent. The soil bore was advanced to a depth of approximately 45 ft. below ground surface and sampled a 5 ft. intervals for TPH, BTEX and Chlorides. Estimated depth to water is greater than 400 ft. The sample results along with a remediation plan and containment upgrade will be submitted to the NMOCD. We will schedule another sampling event in the same area to determine if the vertical extent has migrated further down since the 2nd. Spill event.
The Site remediation for the produced water and crude oil spill will follow the NMOCD guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor: Signed By Mike Brumma	
Title: Waste Mgmt. & Remediation Specialist	Approval Date: 3/3/11	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date: 7/14/10	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

4/3/11

2RP-514