District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District IV 1220 S. St. Francis Dr., Santa Fc, NM 87505

## Energy Minerals and Natural Resources

JUL 15 2010

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

NMOCD ARTESIA

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-31690 Release Notification and Corrective Action										
7 KMW 10.	35627	1612				<b>OPERAT</b>	ΓOR		Initia	al Report
Name of Company BOPCO, L.P. 260 737						Contact Tony Savoie				
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Facility Name Poker Lake Unit 158 Tank Battery						Telephone No. 432-556-8730 Facility Type E&P				
Pacifity Nar	ne Poker L	attery		racility Typ	e E&P					
Surface Owner Federal Mineral Owner						Federal Lease No.				
LOCATION OF RELEASE										
Unit Letter A	Section 7	Township 24S	Range 30E	Feet from the	North/	South Line	Feet from the	East/West Line		County Eddy
Latitude_N 32.237274 Longitude W 103.914835										
NATURE OF RELEASE										
Type of Release: Produced water and crude oil						Volume of Release: 10 Bbls of Produced water and 10 Bbls of Crude oil  Volume Recovered: none				Recovered: none
Source of Release: a 2 3/8" flow line under the facility entrance road						Date and Hour of Occurrence Unkown			Date and Hour of Discovery 7/5/10 8:00 a.m.	
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Left message on NMOCD emergency number.				
						Date and Hour 7/5/10 10:30 a.m.				
By Whom? Tony Savoie Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.				
☐ Yes ⊠ No										
Describe Cause of Problem and Remedial Action Taken.* The flow line delivering produced fluid from the well to the tank battery developed a leak; the temporary repair clamp was placed on the affected area.										
Describe Area Affected and Cleanup Action Taken.*The released fluid affected approximately 600 sq. ft of pasture land and approximately 200 sq.ft. of caliche entrance road. The affected area in the pasture measured approximately 300 ft. long by 2 ft. wide. This spill traveled along the same pathway as a spill reported on 5/8/10, it also connected to an apparent historical spill area. The area was mapped out and samples were collected on 7/14/10 to determine total vertical and horizontal extent.  The Site remediation for the produced water and crude oil spill will follow the NMOCD guidelines for leaks and spills.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.										
						OIL CONSERVATION DIVISION				
Signature: by Danie						Approved by District Supervisor:				
Printed Name: Tony Savoic						Signed By Mile Branca				
Title: Waste Mgmt.& Remediation Specialist						Approval Da	te: <i>3/3/11</i>		Expiration	Date:
E-mail Addre	ess: TASavo	oie@BassPet.	com			Conditions o	f Approval:			Attached
Date: 7/14/10 Phone: 432-556-8730 Remediation per										
Attach Addi	tional She	ets If Necess	ary			PROPOSAL NOT LATER THAN:				