

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 23 2010

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

MYKMW 1035726814

OPERATOR

☒ Initial Report ☐ Final Report



| | | | |
|-----------------|--|---------------|-----------------------------|
| Name of Company | COG OPERATING LLC | Contact | Pat Ellis |
| Address | 550 W. Texas, Suite 100, Midland, TX 79701 | Telephone No. | 432-230-0077 |
| Facility Name | GJ West Coop Unit #210 Tank Battery | Facility Type | Tank Battery |
| Surface Owner | State | Mineral Owner | Lease No. API# 30-015-36703 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| C | 16 | 17S | 29E | | | | | Eddy |

Latitude 32 50.318 Longitude 104 04.987

NATURE OF RELEASE

| | | | | | |
|--|--|---|--------------|--|----------------------|
| Type of Release | Oil | Volume of Release | 15bbls | Volume Recovered | 0bbls |
| Source of Release | Oil Tank | Date and Hour of Occurrence | 06/19/2010 | Date and Hour of Discovery | 06/19/2010 7:00 a.m. |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | | | |
| By Whom? | Date and Hour | | | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |
| If a Watercourse was Impacted, Describe Fully.* | | | | | |
| Describe Cause of Problem and Remedial Action Taken.* | | | | | |
| Oil tank overflowed because oil did not equalize at the same rate as it was being produced. This problem has been corrected. | | | | | |
| Describe Area Affected and Cleanup Action Taken.* | | | | | |
| Initially we released 15bbls out of the oil tank and into the lined facility. All released oil was contained inside the firewalls. The tank will be cleaned, the contaminated gravel will be removed, and fresh gravel will be added to the tank battery. (The closest well location to the tank battery is the GJ West Coop # 210, Unit C, Sec.16-T17S-R29E, 990 FNL 1650 FWL, Eddy County, NM, 32.8391 - 104.08307, API# 30-015-36703) | | | | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | | | | |
| Signature: |  | | | | |
| Printed Name: | Josh Russo | | | | |
| Title: | HSE Coordinator | | | | |
| E-mail Address: | jrusso@conchoresources.com | | | | |
| Date: | 06/23/2010 | Phone: | 432-212-2399 | OIL CONSERVATION DIVISION | |
| Approved by District Supervisor: | | | | Signed By:  | |
| Approval Date: | | | | 3/3/11 | Expiration Date: |
| Conditions of Approval: | | | | Attached <input type="checkbox"/> | |
| Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: 4/3/11 | | | | | |

* Attach Additional Sheets If Necessary

2 RP 527

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Wednesday, June 23, 2010 3:26 PM
To: Bratcher, Mike, EMNRD
Cc: Pat Ellis
Subject: GJ WEST COOP UNIT #210 TANK BATTERY C-141 INITIAL REPORT
Attachments: GJ WEST COOP UNIT #210 TANK BATTERY -- DATE OF RELEASE -- 06-19-2010.PDF

Mr. Bratcher,

Please find attached the C-141 Initial Report for the GJ West Coop Unit #210 Tank Battery. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.