

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

*nkmo 1106147231*

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	OXY USA <i>192463</i>	Contact	Kelton Beaird
Address	1502 W. Commerce Carlsbad, NM 88220	Telephone No. (O)	575-628-4100
Facility Name	Indian Basin Station 128	Facility Type	Production Facility

Surface Owner	Mineral Owner	Lease No. API #	3001532875
---------------	---------------	-----------------	------------

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	28	21S	24E					Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Oil and Produced Water	Volume of Release	44 bbls	Volume Recovered	0
Source of Release	Steel line	Date and Hour of Occurrence		Date and Hour of Discovery	2-6-11 @ 8:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- Left Message, Terry Gregston-BLM		
By Whom?	Kelton Beaird- Oxy	Date and Hour	See above		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

line busted due to freezing temperatures. \*\*API number is for the closest well, which is Indian Hills 53.\*\*

Describe Area Affected and Cleanup Action Taken.\*

Area affected went across the location into an arroyo, through a culvert, under the road and into the pasture. Area on location will be delineated, and a clean-up plan will be submitted for approval. Oxy request to wash the affected area in the pasture, apply fertilizer and bugs, and monitor for re-growth.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *[Signature]*

Printed Name: Kelton Beaird

Title: HES Specialist

E-mail Address: kelton\_beaird@oxy.com

Date: 2-15-11

OIL CONSERVATION DIVISION

Approved by District Supervisor: *[Signature]*

Approval Date: *3/9/11*

Expiration Date:

Conditions of Approval:

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**

Attached ☐

\* Attach Additional Sheets If Necessary

*4/9/11*

*2RP-629*