


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003



Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Yates Drilling company	Contact	Greg Boans
Address	105 South 4 <sup>th</sup> Street, Artesia, NM 88210	Telephone No.	575-748-5363
Facility Name	Robinson "B" Federal #1	Facility Type	Tank Battery

Surface Owner	BLM	Mineral Owner		Lease No.	LC-064073
---------------	-----	---------------	--	-----------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	34	17S	29E	2310	North	2310	West	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	18 bbls	Volume Recovered	10 bbls
Source of Release	Gun Barrel Water Leg	Date and Hour of Occurrence	1:30 PM, 1/22/10	Date and Hour of Discovery	2:00 PM, 1/22/10
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCO Bobby Ballard, BLM Carlsbad, NM			
By Whom?	Greg Boans	Date and Hour 2:08 PM, 1/22/10			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Vacuum trucked recovered 10 bbls fluid and hauled to disposal. Recovered contaminated soil (about 30 yds) and hauled to Lea County Land Farm.

Describe Area Affected and Cleanup Action Taken.\*

Repaired water leg.  
Removed recovered fluid and remediated contaminated soil to Lea Land Farm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Greg Boans

Printed Name: Greg Boans

Title: Production Supervisor

E-mail Address: greg@yates petroleum.com

Date: 1/26/2010 Phone: 575-748-5363

Approved by District Supervisor Mike Bratcher

Approval Date: 3/21/11

Expiration Date:

Conditions of Approval:  
Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:**

Attached ☐

\* Attach Additional Sheets If Necessary

2RP-650