

RECEIVED MAY 19 2010

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-21367

Release Notification and Corrective Action

7 KmW 1107641950

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GJ West Coop South Water Distribution Site	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner	Lease No.
---------------	-------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	23	17S	29E					Eddy

Latitude 32.81225 Longitude 104.0774

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	100bbls	Volume Recovered	10bbls
Source of Release	Transfer Pump	Date and Hour of Occurrence	05/06/2010	Date and Hour of Discovery	05/06/2010 4:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Brucher - OCD			
By Whom?	Josh Russo	Date and Hour	05/07/2010 9:25 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A swedge broke off of the water transfer pump. The swedge has been repaired and the pump has been put back in service.

Describe Area Affected and Cleanup Action Taken.*

Initially 100bbls of produced water was released from the water transfer pump. We were able to recover 10bbls. The spill site area dimensions are 300' x 10'. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the OCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	
Title:	HSE Coordinator	Approval Date:	3/12/11
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	05/07/2010	Phone:	432-212-2399

* Attach Additional Sheets If Necessary

Conditions of Approval:
Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**

Attached ☐

4/12/11

2 PP-647