

RECEIVED DEC 28 2009

District I
1621 N. French Dr., Hobbs, NM 88240
District II
1300 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nkmw/1108952291

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company COG OPERATING LLC	Contact Kanicia Carrillo
Address 550 W. Texas, Suite 100 Midland, TX 79701	Telephone No. 432-685-4332
Facility Name - Willow State #1	Facility Type- Battery

Surface Owner State	Mineral Owner	Lease No. 30-015-28880
---------------------	---------------	------------------------

LOCATION OF RELEASE

Unit Letter O	Section 16	Township 17S	Range 31E	Feet from the 330	North/South Line South	Feet from the 2280	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N32 49.709' Longitude W 103 52.416'

NATURE OF RELEASE

Type of Release- Produced Water	Volume of Release-24 bbls	Volume Recovered- 20 bbls
Source of Release- Water tank	Date and Hour of Occurrence- 12/12/09	Date and Hour of Discovery 12/12/09
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Caused by an electrical problem which was repaired.

Describe Area Affected and Cleanup Action Taken.*

Most of the fluid remained on the pad. About 5 bbls rolled off the pad on the west side of the location into a low spot in the pasture. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for your approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>KC</i>	OIL CONSERVATION DIVISION	
Printed Name: Kanicia Carrillo	Approved by District Supervisor: <i>M. L. B...</i>	
Title: Regulatory Analyst	Approval Date: <i>3/30/11</i>	Expiration Date:
E-mail Address: <i>kcarrillo@conchoresources.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/28/09 Phone: 432-685-4332	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: <i>4/30/11</i>	

* Attach Additional Sheets If Necessary

2RP-676