


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Southwest Royalties, Inc.	Contact	Dawn Howard
Address	6 Desta Drive, Ste 2100	Telephone No.	432/688-3267
Facility Name	North Hackberry Yates Unit #105	Facility Type	Water injection well

Surface Owner	Mineral Owner	Lease No.	NM-06765
---------------	---------------	-----------	----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	23	19S	30E	2310	N	990	E	Eddy

Latitude 32.64674 Longitude 103.92027

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	<20	Volume Recovered	0
Source of Release	FL leak	Date and Hour of Occurrence		Date and Hour of Discovery	12/16/09
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A flowline leak that caused the release of approximately 20 BPM at well #105 location (being approximately 200 yds x 1' wide). The leak has been repaired. Verbal remediation instructions were advised by BLM Environmental representative Justin Frye who was on location 12/16/09.

Describe Area Affected and Cleanup Action Taken.*

Contaminated dirt affected by the spill will be picked up, mixed with new dirt, and replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION Accepted for record NMOCD	
Printed Name: Dawn M. Howard	Approved by District Supervisor:	
Title: Operations Assistant	Approval Date:	Expiration Date:
E-mail Address: dhoward@claytonwilliams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/17/09 Phone: 432/688-3267		

* Attach Additional Sheets If Necessary