

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
**FEB 13 2009**

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company	Mewbourne oil Co.	Contact	Charles Martin
Address	P.O. Box 5270, Hobbs, NM 88241	Telephone No.	(575) 393-5905
Facility Name	Quick Draw 15 G#1	Facility Type	Drilling location
Surface Owner	Chrystine A. Willard	Mineral Owner	Chrystine A. Willard
		Lease No.	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	15	20S	25E	1650'	North	2310'	East	Eddy

Latitude N32°34'33" Longitude W104°28'16"

**NATURE OF RELEASE**

Type of Release	Fresh water based drilling fluid approx 1000 ppm Cl <sup>-</sup>	Volume of Release	unknown	Volume Recovered	0
Source of Release	Temporary pit	Date and Hour of Occurrence	02/09/09	Date and Hour of Discovery	7 pm 02/09/09
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Charles Martin	Date and Hour	8 am 02/10/09		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Problem occurred during the rig move after TD of well. Rig steel pit was accidentally forced across temporary pit wall causing liner to tear and allow release.

Describe Area Affected and Cleanup Action Taken.\*

A leak formed in side wall of temporary pit. An unknown volume of free water released out south wall. Remaining water was removed. Talon lpe was contracted to begin clean-up. Drill cuttings were disposed at Lea Land llc. Moist soil beneath liner was excavated and hauled to Lea land llc. A five point composite sample was taken in the non-impacted area of the floor. A single grab sample was taken below the area of release. Lab results are pending. Upon receipt of results, OCD will be contacted. Hole will be leveled with original material and surfaced with caliche.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Charles L. Martin</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Charles Martin		Accepted for record NMOCD	
Title: Engineer		Approval Date:	Expiration Date:
E-mail Address: cmartin@mewbourne.com		Conditions of Approval:	
Date: 02/11/09	Phone: (575)393-5905	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary