

APPROVED

CARL C. TRAYWICK

Form 9-881a
(Feb. 1961)Budget Bureau No. 42-R358.4.
Form Approved.ACTING DISTRICT ENGINEER
(SUBMIT IN TRIPLICATE)

Land Office

Lease No.

Unit

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

SEP 23 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 2 is located 660 ft. from NORTH line and 2310 ft. from EAST line of sec. 35, 1963
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
 (Field) (County or Subdivision) (State or Territory)
Sitter Lake Chaves New Mexico

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

rigged up cable tool rig over hole, ran tools and tools stopped at 71 feet. after several attempts to drill deeper it was determined that top of last drill pipe was at 71 feet
 set 30 sack cement plug at 71 feet, mudded hole & set 10 sack cement plug at surface & regulation marker

RECEIVED

SEP 23 1963

U. S. GEOLOGICAL SURVEY
ROSWELL, N. M.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company American Employers' Insurance CompanyAddress Box 437
Artesia, New Mexico

By _____

Title _____

Agent

