



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 034932-A
Unit _____

RECEIVED
SEP 24 1961
D.D.S.C.
WELL LOG OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... <input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sep tember 10, 1961

Well No. 1-23 is located 1650 ft. from SS line and 330 ft. from Ex line of sec. 23

SW 1/4 NW 1/4 SW 1/4 23 10-S 25-E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Bitter Lake
(Field)

Chaves
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3553 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Proposing to retreat in effort to make commercial well.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Intex Oil Company

Address Box 122

Midland, Texas

By J. G. Frye

Title Geological Engineer