

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRI  
(Other instructions  
reverse side)DATE  
OR 10-Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

NM 080982

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

---

7. UNIT AGREEMENT NAME

---

8. FARM OR LEASE NAME

Gorman Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Bitterlake SA, South

11. SEC., T., R., M., OR BLM. AND  
SUBVLY OR AREA

Sec. 26, T10S, R25E

12. COUNTY OR PARISH 13. STATE

Chaves

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐2. NAME OF OPERATOR  
Petroleum Corporation of Texas3. ADDRESS OF OPERATOR  
Box 911, Breckenridge, Texas 760244. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

330' FSL and 2310' FEL, Section 26, T10S, R25E

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etc.)

Unknown

Unknown

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☒  
☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent  
to this work.)\*

Moved in 7/22/70 to plug and abandon well:

- (1) Pumped 15 sx. cement @ TD.
- (2) Circulate 10% mud to top.
- (3) Place 2sx. plug @ top of 4" csg.
- (4) Set steel marker.
- (5) Cleaned up location.

Plugging witnessed by USGS representative, Mr. Charley  
Saunderson.

RECEIVED

AUG 20 1970

U. S. GEOLOGICAL SURVEY  
ALBUQUERQUE, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

Mary B. Taylor

TITLE Production Clerk

DATE August 18, 1970

(This space for Federal or State agency use)

APPROVED BY

OFFICIAL OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side