

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico
Lease No. 000000
Unit _____

RECEIVED
FEB 27 1961
D. C. C.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Earl S. Colton - Oil Company-Federal

Feb. 12, 1961

Well No. 1 is located 100 ft. from N line and 900 ft. from E line of sec. 27

10/4 N. 1/4 section 27
(1/4 Sec. and Sec. No.)

10 S 25 E
(Twp.) (Range)

N.M.P.
(Meridian)

N. Airtar Lake
(Field)

Chaves
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3910 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On Nov. 10, 1960 drilled to 700 and ran 7 1/2" 20# casing circulating cement with 300 sacks. Cased on Cement 24 hours and pressured up to 1000# for one hour, logging no pressure decrease. Drilled out and drilled ahead.

RECEIVED

FEB 14 1961

RECEIVED
FEB 14 1961

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Earl S. Colton

Address 1346 Wilson Building

San Antonio, Texas

By Donald L. Hume

Title Agent