



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico

Lease No. 000002

Unit _____

RECEIVED
FEB 27 1961
D. C. C.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Carl A. Colton & Son - Federal

February 13, 1961

Well No. 1 is located 330 ft. from N line and 900 ft. from E line of sec. 27

10 1/4 22 1/4 Section 27

(1/4 Sec. and Sec. No.)

10 S

(Twp.)

25 E

(Range)

N.M.P.

(Meridian)

S. Bitter Lake

(Field)

Chaves

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3510 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Drilled to 981 and, on November 24, ran 97' of 4 1/2" 9.5# casing cementing with 150 sacks. Waited on cement 24 hours then pressured up to 1000# for one hour, logging no pressure decrease.

PRESENTED TO

FEB 14 1961

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Carl A. Colton

Address 1346 Milan Building

San Antonio, Texas

By Donald G. Stearns

Title Agent