

		ACTING

DISTRICT ENGINEER (SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office ~~Las Cruces~~

Lease No. ~~NE 038319-0~~

Unit

RECEIVED

SEP 23 1963

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 20, 1963

Well No. 2 is located 1550 ft. from {N
S} line and 1980 ft. from {E
W} line of sec. 34

Sec. 34 (1/4 Sec. and Sec. No.) Twp. 10 N Range 25 E (Meridian)
Bitter Lake (Township) Chisum Subdivision New Mexico (County)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 150 foot cement plug at total depth, filled hole with sand and set 50 foot cement plug at surface in 4 1/2 inch casing, erected approved dry hole marker, cleaned location

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company American Employers' Insurance Company

Address Box 457

Artesia, New Mexico

By

Title Agent

