

July 28, 1967

Mercury Production Company
1522 Fort Worth Nat'l. Bank Bldg.
Fort Worth, Texas 76102

Re: State E-92 Wells No. 2-F,
7-G and 8-F, 26-10-26,
Brown Pool, Eddy County,
New Mexico

Gentlemen:

A recent field inspection of the subject dry holes revealed the following work to be done before the plugging may be approved. The operators name, lease name, well number, unit letter, section, township and range must be placed permanently on the well marker. A small amount of junk wire, thread protectors, etc., must be cleaned up from around the wells. These locations will be re-inspected after 30 days.

Very truly yours,

Oil Conservation Commission

R. L. Stamets

RLS/jw

Section 1

1. The first part of the document discusses the importance of maintaining accurate records of all transactions.

2. It is essential to ensure that all data is entered correctly and consistently.

Section 2

3. The second part of the document outlines the procedures for handling customer inquiries and complaints.

Section 3

4. This section details the steps for processing orders and managing inventory.

Section 4

5. The final part of the document provides information on reporting and analysis.