

January 6, 1969

Mercury Production Company
508 Fort Worth National Bank Building
Fort Worth, Texas 76102

Re: State E-92 Wells No.
2-F, 7-G & 8-F, 26-10-26,
Brown Pool, Eddy County,
New Mexico

Gentlemen:

On December 10, 1968, an inspection was made of the subject plugged wells. This inspection revealed that the well markers were not completely or accurately identified as required. Please see the attached list for a description of what is currently shown on the marker and what is required to be shown.

At the time of the inspection, I advised your pumper in the field of the additional requirements. A reinspection January 3, 1969, showed that no corrective work had been done.

Please acknowledge receipt of this letter, within 10 days, and advise this office as to what steps are being taken to clear up this matter.

Very truly yours,

OIL CONSERVATION COMMISSION

R. L. Stamets
Geologist

RLS/jw
Enclosure