

# OIL CONSERVATION COMMISSION

207 CARPER BUILDING

ARTESIA, NEW MEXICO

November 30, 1959

Wilson P. Hammond & Son  
P. O. Box 1266  
Monahans, Texas

Dear Sir:

We are returning Forms C-103 on your #2 Alma Shields, well in Sec. 33-7S-27E for some additional information. As per Rule 107 please show the actual time cement was in place before initiating tests. Also the results of casing test, including actual pressure held on pipe and the pressure drop observed.

Very truly yours,

OIL CONSERVATION COMMISSION



W. A. GRESSETT  
Oil & Gas Inspector

WAG/jn  
Enclosures