

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company PAUL SLAYTON				Address 115 E. Country Club - Roswell, N. Mex.			
Lease DIABLO San Andres		Well No. 1	Unit Letter P	Section 16	Township 10S	Range 27E	
Date Work Performed 5/15/68		Pool Diablo San Andres			County Chaves		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain):
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

We pumped 173.56 bbls of 66 gravity oil down the casing to clean up well as this well has 8 5/8 casing, we didn't get distillate very far back into formation, We will repeat this job in a few weeks with about twice as much fluid. We recovered our load oil in about 28 hours and then well dropped back to about 6 bbls per day.

RECEIVED

JUL 10 1968

O. C. C.
ARTESIA, OFFICE

Witnessed by <i>Paul Slayton</i>	Position OPERATOR	Company
-------------------------------------	----------------------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by	Name
Title <i>For Record Only</i>	Position
Date	Company