

OIL CONSERVATION COMMISSION

207 CARPER BUILDING

ARTESIA, NEW MEXICO

October 6, 1959

Mr. William D. Morris
Whaley Company, Inc.
1301-4 Continental Life Bldg.
Fort Worth 2, Texas

Dear Sir:

Enclosed please find (Form C-104) on your N. M. State "A", Well No. 1-A in SW $\frac{1}{4}$ SW $\frac{1}{4}$ of Section 11, Township 11 South, Range 27 East, Chaves County, New Mexico.

We are returning this form due to an error in the information you have given concerning "Oil Well Test". In the blank following (Test After Acid or Fracture Treatment) you have indicated the number of barrels of load oil used. Please correct this to indicate the number of barrels of oil pumped after the recovery of the load oil.

However, before an allowable can be given on this well you must submit three (3) copies for each string of casing, reporting the results of test of casing shut-off.

Yours very truly,

OIL CONSERVATION COMMISSION

M. L. Armstrong,
Supervisor, District No. 2

MLA/jn