

ARTICLE FREE COPY


(SUBMIT IN TRIPLICATE)

Land Office Roswell

Lease No. NM 02272

Unit \_\_\_\_\_

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 2310 ft. from N line and 330 ft. from E line of sec. 20  
NE 1/4 of SE 1/4 11 27 N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Levick Chaves N. Mex.  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Plugged the bottom of the hole at 370' with 15 sacks of cement, at 400' plugged with 10 sacks of cement. Used 10 sacks of cement at top of hole. Filled the balance of the hole with drilling mud. The dry hole has a marker and sign on the lease.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company George H. Williams,

Address 207 W. Ave. B.,  
Lovington, N. Mex.

By George H. Williams

Title \_\_\_\_\_