

Location clean but no
dry hole marker well is probably
not plugged. Well is shut in.

swedge nipple →  casing
10-28-6' 1/2"
L.S.

There is a fenced disposal pit
and a tank battery location south
of this well