

# Oil Conservation Commission

321 Carper Building

Artesia, New Mexico

October 3, 1956

C  
O  
P  
Y

Mr. J. W. Sorrells  
308 Danciger Building  
Fort Worth 2, Texas

Dear Mr. Sorrells:

Our Field Representative, Bill Gressett, checked your Waller Well No. A-1, Unit "P", SE SE Section 28-12S-28E in Chaves County, New Mexico. He found pits not leveled, junk on location and no marker. When marker is placed please put location by quarter-quarter, section, township and range with torch so it will be permanent. When this work is finished, send us Form C-103, Report of Plugging, stating how you plugged the well and that you have cleaned location.

We also need a Form C-105, Well Log, on this well in order to make our file complete. Will you please give this your prompt attention.

Very truly yours,

OIL CONSERVATION COMMISSION

M. L. Armstrong  
Supervisor, District No. 2

MLA/kw

100