

(SUBMIT IN TRIPLICATE)


Budget Bureau No. 42-R358.4  
Approval expires 12-31-60.

Santa Fe, N.M.

Land Office

Lease No. NM-05300 C 29 759

Unit



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

RECEIVED  
FEB 20 1961

SUNDRY NOTICES AND REPORTS ON WELLS

D. C. G.  
ARTESIA, OFFICE

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 1, 1960

Well No. 1 Malco is located 660 ft. from N line and 660 ft. from E line of sec. 15  
C NW 1/4 Sec. 15, 14 South, 28 East, N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Wildcat Chaves New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

9 5/8" casing was cemented from PBTD 1189' to surface.

A 25 sack plug was placed from 1169' to 1114. Heavy mud was used to the surface, 5 sack used at the surface, a marker set and the location cleaned up.

RECEIVED

JUL 5 1960

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Escoba Exploration Company

Address P. O. Box 2184

Abilene, Texas

By [Signature]

Title [Signature]