


Form 9-381a
(Feb. 1961)



APPROVED

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-B386.4
Approval expires 12-31-60.

Land Office **New Mexico**

Lease No. **224-01700-1-A**

Unit **Aug 5 1 23 PM '66**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. **2-22** is located **660** ft. from **[S]** line and **1200** ft. from **[E]** line of sec. **24**
24 (Sec. and Sec. No.) **7-2** (Twp.) **22-5** (Range) **Meridian** (Meridian)
Wilburt (Field) **Chaves** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **4100** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Wilburt Oil Well Drilling Company set the following cement plugs:
2400-2450 (15 ann), 2450-2500 (15 ann) and 25 ann on top of the surface
casing. Grouted a cement in accordance with regulations. Job completed
7:00 AM 12-9-65.**

RECEIVED

AUG 8 1966

O. C. C.

I understand that this plan of work must receive approval in writing by the Geological Survey before work is commenced.

Company **WILBURT OIL COMPANY**

Address **Box 122**

Wilburt, Texas

By **Stewart Martin**

Title **Engineer**