


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office N. M.  
Lease No. 0107847  
Unit K



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 1980 ft. from N line and 1980 ft. from E line of sec. 9  
Jan. 2, 1962  
Wildcat (Field) 140 (Twp.) 29 (Range) NMPM (Meridian) N. M. (State or Territory)  
Chaves (County or Subdivision)

The elevation of the derrick floor above sea level is 3727 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We spotted 25 sxs. cement plugs using Halliburton pump trucks at the following depths; 9894 - 9791, 7784 - 7581, 5740 - 5637, 4050 - 3950, and cemented 4" marker with operators name, well name, footage lines, and legal description. We used a total of 125 sxs. cement with heavy mud between plugs. Did not pull 8 5/8" csg. as it was cemented to surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Philtex Oil Co.  
Address 2510 Mercantile Bank Bldg.  
Dallas 1, Texas

By R. D. Zyman  
Title Agent