



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office S. F.
Lease No. LC-068129
Unit P

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 29, 1963

Well No. 1-A is located 775 ft. from S line and 140 ft. from E line of sec. 21
SE 1/4 6 South 26 East NMPN
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Und. Chaves New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

~~THIS WELL WAS CEMENTED WITH 15 SKE T D, 16 SKE AT 128 FT, 5 SKE WITH MARKER~~
 well was cemented with 15 ske T D, 16 ske at 128 ft, 5 ske with marker
 well was plugged June 12, 1963, pits leveled and marker installed.

Hole is Full mud Between Plugs

RECEIVED

JAN 12 1976

O. C. C.
ARTESIA, OFFICE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company C. D. TurnerAddress Box 1711Big Springs, Texas.

By W. E. Barnes
 Title Representative