

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	1
LAND OFFICE	
OPERATOR	1

RECEIVED

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
K 6183-2

SUNDRY NOTICES AND REPORTS ON WELLS APR - 9 1979

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry hole		7. Unit Agreement Name O.C.C.	
2. Name of Operator Daryl Davis		8. Farm or Lease Name Daryl Davis State	
3. Address of Operator 2615 Simondale Drive Fort Worth Texas 76109		9. Well No. 1	
4. Location of Well UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 1 TOWNSHIP 4 RANGE 26 NMPM.		10. Field and Pool, or Wildcat Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Chaves	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. TD 2078 7"-247- 4 1/2"-2073-250

On April 4, 1979, Panhandle Pluggers Inc. Box 742 Pampa, Texas 79065, moved equipment on the Daryl Davis State well # 1. We ran 42 joints and found a bridge plug @ 1312', pulled 1 joint and pumped 25 sacks of common cement, pulled 11 joints and circulated hole with 9.5 mud. Pulled remainder of tubing and ran 4 joints back in hole and pumped 10 sacks of common cement. Placed 4" marker on hole. Completed on 4-4-79

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Buddy Lomberson TITLE President DATE 4-5-79

OIL AND GAS INSPECTOR

APPROVED BY Mike Stapp TITLE  DATE OCT 3 1979

CONDITIONS OF APPROVAL, IF ANY: