

## OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.O.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

O. C. D.  
ARTESIA, OFFICE

|                                |   |
|--------------------------------|---|
| 5a. Indicate Type of Lease     |   |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No.   |   |

## SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT - "A" (FORM C-101) FOR SUCH PROPOSALS.OIL WELL ☐ GAS WELL ☒ OTHER ☐

Name of Operator

Yates Petroleum Corporation /

Address of Operator

207 South 4th St., Artesia, NM 88210

Location of Well

UNIT LETTER K 1980 FEET FROM THE South LINE AND 1980 FEET FROM  
THE West LINE, SECTION 6 TOWNSHIP 9S RANGE 26E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

Kitchens PH

9. Well No.

1

10. Field and Pool, or Wildcat

Undesignated Abo

11. Elevation (Show whether DF, RT, GR, etc.)

3705.5' GR

12. County

Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐TEMPORARILY ABANDON ☐PULL OR ALTER CASING ☐OTHER ☐PLUG AND ABANDON ☐CHANGE PLANS ☐☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐COMMENCE DRILLING OPNS. ☒CASING TEST AND CEMENT JOBS ☐OTHER Production Casing ☒ALTERING CASING ☐PLUG AND ABANDONMENT ☐☒

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spud at 12 noon 2-10-81.

Drilled plugs as follows: 15' cement plug at surface; tagged plug at 360', 1230', and 4381'.

TD 4707' Ran 122 joints of 4-1/2" 9.5# J-55 casing set at 4707'. 1-guide shoe at 4707'.

Used 2 centralizers. Cemented w/75 sacks Class C and 5# KCL, 400 sacks Class C and

5# KCL. PD 11:00 AM 2-17-81. Ran Temperature Survey and found top of cement at 3515'.

PBD 4713'.

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE Engineering SecretaryDATE 2-19-81

APPROVED BY

TITLE OIL AND GAS INSPECTOR

DATE

FEB 25 1981

CONDITIONS OF APPROVAL, IF ANY: