

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-4036

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

N. King Camp

8. FARM OR LEASE NAME

N. King Camp Unit

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 20, T-13-S, R-29-E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

1. OIL WELL ☐ GAS WELL ☐ OTHER Dry

2. NAME OF OPERATOR

McGrath & Smith, Inc ✓

3. ADDRESS OF OPERATOR

418 Bank of The Southwest, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL and 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

GL 3679

KB 3689

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 3-22-70, Cemented 8 5/8 csg at 228' with 135 sx., circulate
Drilled 7 7/8 hole to T.D. 2120'. Cored Queen 1476-1510; DST 1484-
1510', recovered 90' muddy water and 550' salt water. Spotted cement
plugs as follows: 25 sx 1450-1550'; 25 sx 175-275'; 10 sx 0-20' in
top of 8 5/8. Used Class H Cement, P&A complete 8-26-70. Installed
DHM. Hole between plugs was filled with mud.
Location not cleaned and levelled. Plugs spotted by pump thru drill
pipe.

RECEIVED

NOV 1 1970

U.S. GEOLOGICAL SURVEY
MIDLAND OFFICE

RECEIVED

SEP 3 1970
U.S. GEOLOGICAL SURVEY
ARTESIA FIELD OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED ✓

M. Taylor

TITLE

Supt.

DATE

9-1-70

(This space for Federal or State office use)

APPROVED

SIGNATURE OF APPROVAL, IF ANY:

TITLE

DATE

R. L. BECKMA
ACTING DIRECTOR

*See Instructions on Reverse Side