NO. OF COPIES RECEIV	FD		•		-			Form C-1			
					RE	CEIVED	ΒV	Supersed C-102 an			
DISTRIBUTION		NE	W MEXICO OIL	CONSERV				Effective			
ANTA FE		,	M MEXICO OIL		B .			j			
ILE	-VV				JU	IL 25 198	14	Sa. Indicate	Type of Le	ase	
.s.g.s.		l				~ ~ .		State	1	F••. 🗓	
AND OFFICE		ł			ı	O. C. D.		5. State Oil	& Gas Lear		
PERATOR		j			AR	TESIA, ÓFFIC	E	Fee			
		· · · · · · · · · · · · · · · · · · ·						imm	$m\dot{n}$	mm	
	SUNDR	Y NOTICES	AND REPORTS	S ON WEL	LS				.//////	/////////	
(DO NOT USE TI	USE "APPLICAT	ION FOR PERMIT -	** (FORM C-101) F	OR SUCH PRO	POSALS.)			7. Unit Agre	777777	<i>`</i> 777777777	
Au 577	445 FT							7. Unit Agre	ement Name	•,	
WELL X	WELL	OTHER-									
Name of Operator									8. Farm or Lease Name		
McClellan	Oil Corpo	ration V						Van Eaton-Leyendecker			
Address of Operator								9. Well No.			
P.O. Draw	er 730, Ro	swell, NM	88201	•				1			
Location of Well					· · · · · · · · · · · · · · · · · · ·			10. Field on	_		
	L ·	1980	PROM THES	outh		660		Wildca	at-Mont	oya	
UNIT LETTER	•		PROM THE	·	!HE AHD		EET FROM	mm	777777	mm	
West	•	. 22		6 - S	*	27-E			(((((
THE	LINE, SECTION	pvi ————	TOWNSHIP		RANGE		нмрм.				
mmm	rimm	· · · · · · · · ·	Elevation (Show w	hacker DE	RT CR 44	. 1		12. County	<i></i>	++++++	
		///////////////////////////////////////	4149'		its, on, en	.,	•	Chave			
777777777			- 					011416		77777777	
•	Check ,	Appropriate	Box To Indica	ate Natw	e of Not	ice, Repor	t or Oth	er Data			
N	OTICE OF I	TENTION T	0:	1		SUBSI	EQUENT	REPORT	OF:		
						•					
ERFORM REMEDIAL WO	•× 🔲	·	PLUG AND ABANDON	(AE)	AEDIAL WORL	ĸ			LLTERING CA	SING	
EMPORARILY ABANDON	Ħ			-	MMENCE DRI	LLING OPHS.	Ħ		LUG AND AB	ANDONMENT T	
JLL OR ALTER CASING			CHANGE PLANS	<u> </u>		ND CEMENT JOB	\square				
702 ON AC1211 CAD11110	ب			— i	от <u>нея</u>			acidize		. \Box	
OTHER	-2		•		V1,012			,, 	- 1		
V1767											
. Describe Proposed	or Completed Or	perations (Clear)	y state all pertine	nt details,	and give pe	rtinent dates,	including	estimated da	e of startin	ig any proposed	
work) SEE RULE	1 103.				ř						
		ž.			•						
7 /3 1 /0/ .	Dane at (~404 OF O7	07 2 100	r Aoi	d:	طائن مص	E00 as	1 1 1 5 0 1	MCA and	4	
7/11/84:			,87 - 2 JSP	r. ACI	dize zo	me with	ouu ya	15. 15%	MUH act	a.	
•	Swapped r	back load.									
				_			_			. •	
7/12/84:	No gas, 1	flund leve	1 400' from	surrac	e. 511	gnt snow	or gas	s. Swab	pea 120	, _	
	of salt h	$1_{0}0$ with .	1% oil cut.	Ran C	IBP 648	34'. Ran	15' 01	fcement	on top	of	
	CIBP.	_									
		gar"									
7/16/84:	Perf from	n 6457,5 8,	59. Ran 50	O gals.	15% MC	CA acid.	Swabbe	ed back	acid lo	ad.	
	Could not	t swab belo	ow 3000'.	No oil.							
					1,00	(ABO)					
7/18/84:	Set CIBP	at 5150'.	Perf from	50391-	5044 -	· 8 holes	. Acid	dize zon	e with	500 4	
,,_,,	gals, 10%	MCA acid	. Swab loa	d back.	Show	of das.	Next	reports	to sh	ow Abo	
	34.00 20,					o. 3.00		7		.,	
•							•				
. I hereby certify the	t the information	above is tone	nd complete to the	heat of m-	knowleden	and hall-f					
	, /	·	somposts to the	сти от шу	-un-seake	Dellel.					
- S	A	پر پر کھی ۔		Drad	uction	Engineer			7/20/0	RΛ	
:NED	(CTC)	ree	TITLE	- 1 1 Uu	4001011	Lingtheel		. DATE	7/20/8)T	

		OPICINAL	L SIGNED						AUG	1 1984	
PROVED BY	Z.		BROOKS TITLE			·		DATE		- 1007	
	ROVAL, IF ANY		T - NMOCD								