

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instructions
reverse side)TE*
reForm approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 17576

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

RECEIVED

7. UNIT AGREEMENT NAME

JUL 15 1981

8. FARM OR LEASE NAME

Isler Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT
Undesignated Granite Wash11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 6, T7S, R27E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

Sanders Petroleum Corporation ✓

3. ADDRESS OF OPERATOR

11000-D Spain Road NE, Albuquerque, NM 87111

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 1980' FWL, Sec. 6, T7S, R27E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3913-GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Run Casing & Cement

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

7-8-81 Current Depth 1772'. Ran 45 joints 8-5/8" 24# J-55 casing, set at 1772'.
Plugg down at 9:00 a.m. 7-7-81. Temp. survey 530' at 4 a.m. Cemented with 610 sx. 63/35
Poz. 6% gel, 8# Kolite, 1/4# Celloflake, 5# Salt, 3% CaCl₂ plus 200-sx. "C" 2% CaCl₂
7-9-81 Current Depth 1772'. Temp. survey 530'. Cemented with Class "C" 4% plus CaCl₂
as follows:

Stage #	# of sx.	Footage/top of cement
1	50	530'
2	100	510'
3	100	500'
4	50	470'

7-10-81 Finished cementing thru 1" pipe as follows:

Stage #	# of sx.	Footage/top of cement
5	50	470'
6	50	470'
7	50	350'
8	50	320'
9	50	320'
10	50	300'
11	50	270'
12	50	230'
13	150 - circ. out 35 sx.	

Tested casing & B.O.P. to 1200 psi before drilling
out.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Assistant

DATE 7-10-81

(This space for Federal or State Office Record)

APPROVED BY ROGER A. CHAPMAN
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JUL 13 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side