

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. Oil well ☐ Gas well ☒ other

2. NAME OF OPERATOR
MESA PETROLEUM CO. ✓

3. ADDRESS OF OPERATOR
1000 VAUGHN BUILDING/MIDLAND, TEXAS 79701-4493

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL & 660' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: SAME

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

(other) 8 5/8" csg & cement

SUBSEQUENT REPORT OF:

SEP 2 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

NOTE: Report results of multiple completion or zone change on Form 9-330.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Drilled 11" hole to 1720' and ran 39 jts 8-5/8", 24#, K55 casing set at 1720'. Cemented with 750 sx HLW + 1# Flocele + 4% CaCl, 300 sx Thixset + 4% CaCl, and tailed in with 300 sx "C" + 2% CaCl. PD at 2:00 a.m. 8-29-81. Circulated 100 sx. Reduced hole to 7-7/8", tested BOP's to 600 psi for 30 min-OK, and drilled ahead on 8-29-81. WOC total of 19 hours.

OS 1385 13, TUS, GEN RODS, ACCTG MEC, LAND, PARTNERS, ROSWELL, FILE
Subsurface Safety Valve Make and Type _____ Set _____

18. If necessary, ACCEPTED FOR RECORD true and correct

SIGNED PROPER P. RICHMAN

REGULATORY COORDINATOR

9-1-81

SEP 3 1981

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

TITLE _____ DATE _____