YGOD, GODY

	•
Form 9-331 UNITED STATES SUBMIT IN TRIPLICATE* (May 1963) (Other instructions on re-	Form approved. Budget Bureau No. 42-R1424.
DEPARTMENT OF THE INTERIOR (Other Instructions on re-	5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY	NM-13978 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	d, ir indian, abbotted on labe name
JUN 2 6 1931	7. UNIT AGREEMENT NAME
WELL WELL A OTHER 2. NAME OF OPERATOR O. C. D.	8. FARM OR LEASE NAME
McClellan Oil Corporation /	Leeman federal
3. ADDRESS OF OPERATOR	9. WELL NO.
Post Office Drawer 730, Roswell, New Mexico 88201. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	88201 10. FIELD AND POOL, OR WILDCAT
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface	Wildest Had alm
At surface	11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA
1980' FSL & 1680' FEL	47.5
	Sec. 1-T9S-R25E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OF PARISH 13. STATE Chaves New Mexi
3657' Gr.	Chaves New Mexi
6. Check Appropriate Box To Indicate Nature of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO:	UENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING Product 1	on casing X
REPAIR WELL CHANGE PLANS (Other)	of multiple completion on Well
(Other) FETTOTALE & COMPTECE 12 Completion or Recomptered proposed work. If well is directionally drilled, give subsurface locations and measured and true vertices.	oletion Report and Log form.) , including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertice nent to this work.) *	all depths for all markers and zones perti-
6/13/81: Drilled to total depth of 4600'. Ran Schl	umberger CNL-FDC.
6/14/81: Micro-SFL Dual Laterolog.	
6/15/81: TD 4600'. Ran 117 joints 4½", 10.5#, J-55 Cemented with 250 sx Class "C" 50-50 Poz, .3% Halad-4, .3% CFR-2. Plug down at 2:00 Temperature survey TD 4520'. Top of cemen	2% gel, 6# salt, 0 P. M. 6/15/81.
Prep to perforate and attempt completion o	on June 22, 1981.
ACCEPTED FOR RECORD	
ROGER A. CHAPMAN	
JUN 23 1981	JUN 1 9 1981
U.S. GEOLOGICAL SURVEY	J. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO	ROSWELL, NEW MEXICO
18. I hereby certify that the foregoing is true and correct Secretary	June 16, 198
SIGNED 4 A A TITLE	DATE
(This space for Federal or State office use)	
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE
CONDITIONS OF WEIPOARD IN WHI.	