STATE OF NEW ME	EVICO						
		-					
ERGY AND MINERALS DE			CONSERV				
NO. OF CONSER RECEIVED				ATION DIV	REIGNO		Form C-103
DISTRIBUTION		-4		OX 2088			Revised 10-1-
SANTA FE		SA	NTA FE, NE	W MEXICO 8		•	
/ ILE	11/	-	•	JU	N 241981	Sa. Indicate Type	of Lease
U.S.G.S.		-				State	F X
LAND OFFICE		·		ſ	n an th	5. State Oil 6 Ga	s Legae No.
OPERATOR	1/1_	J					
<u></u>				781	LSIA, OFFICE	Lauran	mmm
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFPIN OR PLUG DACK TO A DIFFERENT RESERVOIR. 100 NOT USE THIS FORM FOR PROPOSALS.							
	APPLICAT	TION FOR PERMIT -	(FURM C-101) FOR 5	UCH PROPUSALS.		7. Unit Agreement	<u> </u>
		OTHERS					
ne of Operator						8. Farm or Lease	Name
Stevens 0il Company						O'Brien 'FF''	
ress of Operator	Jonpar	··· <i>y</i>				9. Well No.	
P. O. Box 22	, a 20	orunii Nou M	Arrian 88201			1	
P. U. DOX 22	.05, M	USWELL, NEW I	EATCO 00201			10, Field and Poo	ol, or Wildcat
					·1-	4 Twin Lakes	-San Andres
NIT LETTERJ	· • ·	2310 PEET PR	OM THE South	L	FEET FROM	ASSOC	mmm
						V	///////////////////////////////////////
East	INE, SECTI	ION6	TOWNSHIP 95	RANGE	<u>29E</u> NMPM.	VIIIIII	
······································		· · · · · · · ·					MMMM
15. Elevation (Show whether DF, RT, GR, etc.)						12. County	
	11111	3955	5.1 GR, 3960	.1.KB		Chaves	
mmm	دددد				·	· · · · · ·	
		••••	x lo indicate	Nature of Not	ice, Report or Otl		
NOTIC	E OF H	NTENTION TO:			SUBSEQUENT	REPORT OF:	
				1			_
· · · · ·	1		ر	¬!	Γ Ì		1
DAM REMEDIAL WORK		PL	UG AND ABANDON	REMEDIAL WORK		ALTER	
		Ρι	UG AND ABANDON	REMEDIAL WORK	T T		ING CASING
ORARILY ABANDON	}		UG AND ABANDON	-1	LING OPNS.	PLUG A	ND ABANDONMENT
ORARILY ABANDON]			COMMENCE DRIL	LING OPHS.	PLUG A	7
ORM REMEDIAL WORK]			COMMENCE DRIL	LING OPNS.	PLUG A	ND ABANDOHMENT

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 6-11-81 Spud. Ran 3 joints 8 5/8" 20# surface casing, set in cement at 134' with 75 sacks Class "C" and 1% calcium chloride, circ. 20 sx. WOC 18 hrs. Pressured up to 1000# for 30 min., logging no pressure decrease.
- 6-19-81 Ran 72 joints of 4 1/2" 9.5# casing, set in cement at 2878' with 200 sacks self stress, 2% calcium chloride. WOC 18 hrs. Pressure up to 1000# logging no pressure decrease.
- 6-22-81 Perforated 2696, 96.5, 97, 2704.5, 05, 05.5, 2708, 08.5, 2710, 10.5, 2714, 14.5, 15, 271715, 18, 18.5, 2722, 22.5, 23, 2726, 26.5. Ran 84 joints, set packer at 2566'. Acidize with 9000 gals 28% and 21 balls.

hereby fertily that the information above is true and comp	plete to the bes	t of my knowledge and belief.	<u></u>	
. Janal Sipta		Owner	DATE	6-23-81
Mule Williams	TITLE	OIL AND GAS INSPECTOR	DATE_	JUN 2 5 1981