STATE OF NEW MEXICO	•
OFE CONSERVATION DIVISION	
F. O. BOX 2008	Form C-103 Revised 10-1-78
SANTA FE, NEW MEXICO 87501	
U.S.G.J.	Se. Indicate Type of Leose
LAND OFFICE	Stene Free 🔀
OPERATOR	S. Siere OLI & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED	
	7. Unit Agreement None
JUN 27 '88	TLSAU
(none of Operator	8. Farm or Lease liane
Pelto Oil Company V O. C. D.	
1. Address of Cporetor D. C. D. ARTESIA, OFFICE	9. Well Na.
500 Dallas, Suite 1800, Houston, TX 77002	73
<. Lecature of well	10. Pleid and Pool, or Wildcat
VHIT LETTER E 1650 FEET FROM THE N LINE AND 330 FEET FROM	Twin Lakes SA Assoc.
THE WLINE, SECTION 5 TOWASHIP 95 AANSE 29E HAPA.	
396 (Star	12. County Chaves
Check Appropriate Box To Indicate Nature of Notice, Report of Oth NOTICE OF INTENTION TO: SUBSEQUENT	
-CAP MAN BENEDIAL WORK	ALTEPING CASING
•THERO	jector X

7. Describe Preseed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1983.

- 12-10-87 RU PU (Monument). Ran 4 1/2" scraper & 3 7/8" bit on 2 3/8" WS to tag PBTD @ 2865'. Had to work through tight spot @ 2590'. Scraper & bit hung up again coming out. Prep to test csg & log.
- 12-11-87 Ran a 4 1/2" Guiberson Uni-6 BP & pkr on 2 3/8" workstring. Set BP @ 2726'. PU & set pkr @ 2716'. RU Goldstar. Press tested between BP & pkr. Held 500#. Loaded csg-tbg annulus w/FW & could not get annulus to hold 500#. Worked pkr up the hole & isolated a csg leak between 1830-1860'. Pumped FW into csg leak @ 1/4 BPM @ 400# with pkr above leak @ 1830' we still could not hold 500# on annulus. There is another small leak above 1830'. Approx 1/8 BPM @ 500#. Pulled tbg & pkr. RU CRC. Ran free pipe log & found TOC @ 2034'. SDON. We need to know if TOC has to be 500' above top perf or 500' above top of San Andres.

12-14-87 SD due to weather.

12-15-87 Pulled tbg, BP & pkr. RDPU. Waiting to find out what to do with csg leaks.

to Servi 2	the above is the and complete to the best of my knowledge and belief.	c6-20-88
	Original Signed By Mike Williams Oil & Gas Inspector	JUN 2 9 1988

- 5-5-88 RU Schlumberge Set CIBP @ 2710'. RD Schlumbe er.
- 5-14-88 RU Schlumberger. Ran pipe analysis log & caliper. RD Schlumberger.
- 5-17-88 RUPU (Monument). Ran Guiberson Uni-6 BP & pkr on 2 3/8" workstring. Set BP @ 2708'. Worked pkr up hole testing possible holes indicated on Schlumberger pipe analysis log. Csg tested good from BP @ 2708' to 1877'. With pkr @ 1846', we could pump into leak between 1846' & 1877' @ 300#. Lowered tbg & pkr. Latched on BP. PU & set BP @ 1877'. Pulled 1 jt & set pkr @ 1846'. Press tested between BP @ 1877' & pkr @ 1846'. We could pump into leak @ 300#. Lowered pkr & re-set @ 1860'. Started pumping down tbg below pkr & got communication up csg-tbg annulus. Picked pkr back up to 1846' & re-set. Still got communication up csg-tbg annulus. Pulled tbg, pkr & BP. SDON.
- 5-18-88 WIH w/Guiberson Uni-6 BP & pkr. Set BP @ 1877'. Worked pkr up hole & isolated leaks @ 1840' & 1870'. Tested csg up to 1000' from surface. Csg held 500# from above leak @ 1840' to 1000'. Have another leak above 1000'. Pulled tbg, pkr, & BP. WIH w/tbg & pkr. Set pkr @ 1811'. Started pumping. Circ to surface out bradenhead. SDON.
- 5-19-88 WIH w/tbg open ended. Tagged CIBP @ 2710'. PU to 2708'. RU Halliburton. Dumped 50 sx Class C neat cmt on top of CIBP. Pulled tbg. WIH w/4 1/2" cmt retainer on tbg & set ret @ 1811'. Started pumping FW in an attempt to get circ through holes & up bradenhead. RU Goldstar pump truck. Put 800# on 4 1/2" csg while pumping down the tbg @ 1400# before breaking through an apparent bridge & getting circ. After circ 17 bbls press dropped to 500# @ +.5 BPM. Started mixing & pumping 200 sx Class C neat cmt. Lost circ before cmt got to retainer. Kept pumping cmt, regaining circ from time to time. Pumped 194 sx through hole up 7 7/8" open hole & into salt section or some other zone. SD pump. Flushed lines. Staged 4 1/2 sx into hole until we got it to hold 200#. Pulled tbg & stinger leaving about 30' cmt on top of retainer. SDON.
- 5-20-88 PU & ran3 7/8" bit on WS to tag TOC @ 1799'. Pulled tbg & bit. PU & ran Uni-IV pkr. Set pkr @ 103'. Could not press up. Communicated out csg. Lowered pkr 1020' & press up to 400#. Held OK. Pulled tbg & pkr. SDON. Gold Star had equip problems & could not press up on csg.
- 5-23-88 RU Gold Star pump truck. Press tested csg from TOC @ 1799' to surface @ 500#. Held good. Prep to drill out cmt. SDON.
- 5-24-88 RU Star Tool. PU & ran 3 7/8" bit, 6 collars on 2 3/8" tbg to tag TOC @ 1799'. Drilled through cmt retainer & cmt to 1879' & fell through. Lowered tbg & bit to tag CIBP @ 2712'. Press up csg between CIBP & surface @ 400#. Held OK. SDON.
- 5-25-88 Drilled on CIBP for 2 hrs. TOOH, replaced bit. Went back in hole w/bit, 6 DC's & 2 3/8" WS. Finished drilling up CIBP. Lowered tbg to 2868'. Circ hole clean. Pulled tbg, DC's & bit. Started in hole w/Halliburton R-4 pkr & 2 3/8" plastic coated inj tbg. SDON.
- 5-26-88 Finished running total of 85 jts (2728') 2 3/8" plastic coated tbg. Pumped 10 bbls corr inhib wtr down csg-tbg annulus. Set pkr open ended on btm of string @ 2735'. Loaded annulus w/inhib wtr. Press test @ 300#. Had slow leak. Pulled 1 jt & tried to re-set pkr. Still would not hold. Pulled tbg & pkr. SDON.
- 5-27-88 PU & WIH w/4 1/2" csg scraper, 3 7/8" bit & tbg to 2769'. Pulled tbg, scraper & bit. WIH w/another 4 1/2" Halliburton R-4 inj pkr & 84 jts (2697') 2 3/8" plastic coated inj tbg. Set pkr open ended on btm of string @ 2703'. Loaded csg-tbg annulus w/inhib wtr. Press tested csg & pkr @ 300#. Ran chart 30 min. Held OK. RDPU. JOB COMPLETE.