

B. Soil: Sandy loam

C. Flora and Fauna: The flora consists of typical desert vegetation, such as yucca, mesquite, cactus and various grasses. Fauna consists of desert wildlife such as coyotes, rodents and snakes. Dove and quail were noted in the area.

D. Ponds or Streams: A stock pond is located about 1/4 mile northwest of the location.

E. Residences and other Structures: A feed barn is located about 1/4 mile north of the location. The nearest dwelling is about 4 miles northwest.

F. Archaeological, Historical and other Cultural Sites: No artifacts were noted in the area of the pad or access roads. An Archaeologist from Eastern New Mexico University has been contracted to conduct a survey and report regarding possible cultural disturbance. The report will be furnished to BLM for appropriate recommendations.

G. Land Use: Grazing

H. Surface Ownership: The well is located on Public surface. Part of the access road is on fee land.

12. OPERATOR'S REPRESENTATIVE:

Dan Needham  
P.O. Box 1323  
Roswell, N.M. 88201

13. CERTIFICATION:

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drillsite and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge true and correct; that the work associated with the operations proposed herein will be performed by

