

NM OIL CONS. COMMISSION
Drawer DD
Artesia, N.M. 88210

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

C/SF
SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
MESA PETROLEUM CO. ✓

3. ADDRESS OF OPERATOR
1000 VAUGHN BUILDING/MIDLAND, TEXAS 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL & 1980' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) SPUD, 13 3/8" CSC & cement

SUBSEQUENT REPORT OF:

RECEIVED
SEP 23 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded well with 12 1/4" hole on 8-29-81. Stuck pipe at 749', fishing and reaming out hole to 17 1/2" until 9-14-81. Ran 21 jts 13 3/8", 48#, H-40 casing set at 888'. Cemented with 800 sx HLW + 1# flocele + 4% CaCl₂, 300 sx Thixset + 4% CaCl₂, and tailed in with 250 sx "C" + 2% CaCl₂. PD at 2:30 AM 9-16-81. Cement did not circulate. Ran temp survey - TOC at 700'. Set 13 plugs with a total of 2550 sx Thixset + 6 yds - Redi-mix to circulate cement. Reduced hole to 11" and drilled ahead on 9-19-81.

XC: USGS (6), TLS, GEN RCDS, ACCTG, MEC, ~~XXXX~~, PARTNERS, ROSWELL, FILE
Subsurface Safety Valve: Make and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED ROGER A. CHAPMAN

TITLE REGULATORY COORDINATOR DATE SEPTEMBER 22, 1981

APPROVED BY _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY

SEP 24 1981
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO