

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
2. NAME OF OPERATOR
MESA PETROLEUM CO. ✓
3. ADDRESS OF OPERATOR
1000 VAUGHN BUILDING/MIDLAND, TEXAS 79701
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FSL & 1980' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

SPUD, 8 7/8" CSG CEMENT

RECEIVED
SEP 28 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

5. LEASE
NM-36651
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
CINDY FEDERAL
9. WELL NO.
2
10. FIELD OR WILDCAT NAME
UNDESIGNATED ABO
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SEC 24, T8S, R22E
12. COUNTY OR PARISH
CHAVES
13. STATE
NEW MEXICO
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3986.5' GR

RECEIVED

OCT - 5 1981

O. C. D.
ARTESIA, OFFICE

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded well with 12 1/4" hole on 9-17-81. Drilled to 1492' and ran 34 1/2" 8 5/8", 24#, k55 casing set at 1484'. Cemented with 800 sx HLW + 1# Flocele + 4% CaCl, 300 sx Thixset + 4% CaCl, and tailed-in with 200 sx "C" + 2% CaCl. PD at 10:00 p.m. 9-20-81. Circulated 400 sx to surface. Tested BOPs and casing to 600 psi for 30 min-OK. Reduced hole to 7 7/8" and drilled ahead on 9-21-81. WOC total of 18 hours.

XC: USGS (6), TLS, CEN RCDS, ACCTG, MEC,
Subsurface Safety Valve: Manu. and Type _____

PARTNERS, ROSWELL, FILE

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

ROBERT A. BIERMAN

REGULATORY COORDINATOR

DATE

9-23-81

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

SEP 30 1981

TITLE

DATE