

SUNDRY NOTICES AND REPORTS ON WELLS

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
MESA PETROLEUM CO. ✓

3. ADDRESS OF OPERATOR
1000 VAUGHN BUILDING/MIDLAND, TEXAS 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FNL & 660' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) SPUD, 13 3/8"

SUBSEQUENT

[illegible]

REPORT OF
RECEIVED
OCT 13 1981
NOTE: Repro
chan

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded well with 17 1/2" hole on 9-28-81. Stuck pipe and re-worked hole until 10-5-81. Ran 19 jts 13 3/8", 48#, H-40 casing set at 826'. Cemented with 800 sx HLW + 4% CaCl, 300 sx Thixset + 4% CaCl, and tailed in with 200 sx. Reduced hole to 11" and drilled ahead on 10-6-81. WOC total of 18 hours. Circulated 200 sx of cement.

XC: USGS (6), TLS, CEN RCDS, ACCTG, MEC, LAND, PARTNERS, ROSWELL, FILE
Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

ACCEPTED FOR REVISION
ROGER A. CHAPMAN

REGULATORY COORDINATOR

DATE OCTOBER 9, 1981

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF

OF APPROVAL, IF ANY:

TITLE

DATE _____

U.S. GEOLOGICAL SURVEY
ROS WELL, NEW MEXICO

*See Instructions on Reverse Side