

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

C/SF
SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR
MESA PETROLEUM CO. /
3. ADDRESS OF OPERATOR
1000 VAUGHN BUILDING/MIDLAND, TEXAS 79701
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL & 660' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA


REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

TD, 4 1/2" csg & cement



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

5. LEASE
NM-14993
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME **RECEIVED**
8. FARM OR LEASE NAME **NOV 17 1981**
SAVAGE FEDERAL
9. WELL NO. **O. C. D.**
3 **ARTESIA, OFFICE**
10. FIELD OR WILDCAT NAME
UNDESIGNATED ABO
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SEC 4, T7S, R25E
12. COUNTY OR PARISH **CHAVES** 13. STATE **NEW MEXICO**
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3810' GR

NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 7-7/8" hole to TD of 4160' on 11-8-81. Ran 102 jts 4 1/2", 10.5#, k55 casing set at 4152'. Cemented with 500 sx HLW + 10# salt + 1/4# Flocele and tailed in with 500 sx "C" + 5# KCL + 3/10% HALAD-4 + 2/10% CFR-2. PD 12:00 p.m. 11-8-81. Cement did not circulate. Released rig at 6:00 a.m. 11-9-81. WOCU estimated to arrive 11-16-81.

XC: USGS (6), TLS, CEN RCDS, ACCTG, MEC, LAND, PARTNERS, ROSWELL, FILE

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

R. E. Valt

REGULATORY COORDINATOR

DATE 11-11-81

ACCEPTED FOR RECORD
APPROVED BY **ROGER A. CHAPMAN**
CONDITIONS OF APPROVAL, IF ANY:

(This space for Federal or State office use)

TITLE

DATE

NOV 16 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side