

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

C/SF
SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

2. NAME OF OPERATOR
Husky Oil Company

3. ADDRESS OF OPERATOR
600 S. Cherry St., Denver, CO 80222

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2050' FNL & 2100' FEL, SW $\frac{1}{4}$ NE $\frac{1}{4}$
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* Ran Production Casing
(other)

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Ran 89 jts 4 $\frac{1}{2}$ " 10.5# K-55 ST&C csg. Set @ 3848' KB. Cemented w/330
sx 50/50 Pozmix Class "C" + .6% CF9 + .3% TF-4 + 3% KCl. Displaced
w/61 bbl brine. Bump plug @ 1400 psi, o.k. CIP @ 10:30 a.m. 11/25/81.

Rig Released @ 10:30 a.m. 11/25/81.

RECEIVED
DEC 04 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

Subsurface Safety Valve: Manu. and Type _____

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED ROGER A. CHAPMAN

for Jim Yates
TITLE Drilling Engineer DATE December 1, 1981

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:
DEC 11 1981
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

(This space for Federal or State office use)

TITLE _____ DATE _____