88310

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES Artenia, Sie

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5.	LEASE	

O WELL NO

___NM_9813

8. FARM OR LEASE NAME South Alkali LK Federal

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

JAN 1 3 1982

Other/1

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
~~					

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)

1.	oil well		gas well	X	other	
2.	NAM	E OF Yate	OPERA	ror rol	eum Corporation	-

3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1980 FSL & 1980 FWL AT SURFACE:
AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

9. WELL NO.	V ₁₀ 2.
3	ARTEMA
10. FIELD OR WILDCAT N	AME
and Wildest Abo	
11. SEC., T., R., M., OR E AREA / Unit / Sec. 11-6	
12. COUNTY OR PARISH Chaves	13. STATE NM
14. API NO.	

15. ELEVATIONS (SHOW DF, KDB, AND WD) 3884 GR

•	
REQUEST FOR APPROVAL TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)	г о:

(NOTE: Report results of multiple completion or zone

JAN -6 1982 charge on Form 9-330.)

OIL 8 GAS

U.S. OFOLOGICAL SURVEY

HOSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SUBSEQUENT REPORT OF:

Set 40' of 20" conductor pipe. Spudded 14-3/4" hole at 12:30 PM 12-10-81. Ran 22 joints of 10-3/4" 40.5# J-55 casing set at 925'. 1-Texas Pattern guide shoe at 925'. Flapper insert float at 883'. Cemented w/400 sacks Pacesetter "C" 3% CaCl₂. Tailed in w/300 sacks Class "C" 2% CaCl₂. PD 11:45 PM 12-12-81. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 35 sacks to pit. WOC. Drilled out at 6:45 PM 12-13-81. WOC 18 hours. Nippled up and tested to 1000 psi, OK. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu, and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED TITLE Engineering Secty DATE	1-4-82
APPROVED BY DATE DATE	
U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO See Instructions on Reverse Side	