STATE OF NEW MEXICO				
ENERGY AND MINERALS DEPARTME	NT			
	DIL CONSERVA		Form C-103	
DISTRIBUTION	Р. О. ВО			
SANTAFE /	SANTA FE, NEW	MEXICO 87501	Revised 10-1-78	
FILE 1-	1	· · · · · · · · · · · · · · · · · · ·	5a, Indicate Type of Lease	
U.3.G.S.		JAN 4 1982	State Fee X	
LAND OFFICE		JAN 4 1302	5. State Oil & Gas Lease No.	
OPERATOR /)			
		<u> </u>	humminning	
IDO NOT USE THIS FORM FOR PRO	Y NOTICES AND REPORTS ON	WELLERTESIA, OFFICE	λ	
.1,			7. Unit Agreement Name	
OIL GAS X	01454-			
2. Name of Operator			8. Farm or Lease Name	
Yates Petroleum Co	Finley PV Com			
			9. Well No.	
3. Address of Operator	1			
207 South 4th St.,	Artesia, NM 00210		10. Field and Pool, or Wildcat	
4. Location of Well		1080	Und. Abo	
UNIT LETTER	1830 FEET FROM THE	LYOU FEET FROM		
			<u> </u>	
West	ON 34 TOWNSHIP 65	25E		
THE CINE, SECTION	ON TOWNSHIP		(1)	
THIMIN INTO INTO INTO INTO INTO INTO INTO IN	12. County			
	15. Elevation (Show whether 3721' GR		Chaves ())))))))	
Junninnin			D	
	Appropriate Box To Indicate N			
NOTICE OF IN	NTENTION TO:	SUBSEQUENT	REPORT OF:	
			(—)	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ASANDON		COMMENCE DRILLING OPHS.	PLUG AND ASANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB X	· ·	
		OTHER		
OTHER				

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEZ RULE 1103.

Set 40' of 14" conductor pipe. Spudded a 12-1/4" hole at 11:00 AM 12-22-81. Ran 20 joints of 8-5/8" 24# casing set at 805'. 1-Texas Pattern notched guide shoe at 805'. Insert float at 765'. Cemented w/200 sacks Thick-set 3% CaCl₂, 300 sacks Halliburton Lite w/2% CaCl₂. Tailed in w/300 sacks Class "C" 2% CaCl₂. PD 4:45 PM 12-24-81. Bumped plug to 750 psi, released pressure & float held okay. Cement did not circulate. WOC 40 hours & 45 minutes. Ran 1". Spotted 100 sacks Thick-set 3% CaCl₂. PD 10:30 AM 12-26-81. WOC 2 hours & 15 minutes. Ran 1". Spotted 75 sacks Class "C" 2% CaCl₂. PD 1:00 PM 12-26-81. WOC 1 hour & 45 minutes. Ran 1". Spotted 75 sacks Class "C" 2% CaCl₂. PD 4:30 PM 12-26-81. WOC 1 hour & 45 minutes. Ran 1". Spotted 75 sacks Class "C" 2% CaCl₂. PD 4:30 PM 12-26-81. Cement was brought to surface. WOC. Drilled out at 2:30 AM 12-27-81. WOC 57 hours & 45 minutes. Nippled up & tested to 1000 psi, 0K. Reduced hole to 7-7/8". Drilled plug & resumed drilling. Lost circulation. Set lost circulation plugs as follows: Plug #1: 250 sacks Thick-set 4% CaCl₂. Tailed in w/150 sacks Class "C" 4% CaCl₂. PD 4:30 PM 12-27-81. Plug #2: 250 sacks Thick-set 4% CaCl₂. Tailed in w/150 sacks Class "C" 4% CaCl₂. PD 4:30 PM 12-27-81. Plug #2: 250 sacks Thick-set 4% CaCl₂. Tailed in w/150 sacks Class "C" 4% CaCl₂. PD 5:00 PM 12-28-81. Set lost circulation plugs at 806' as follows: Plug #3: 100 sacks Class "C" 4% CaCl₂. PD 10:30 PM 12-29-81. WOC 2 hours & 45 minutes. Plug #4: 100 sacks Class "C" 4% CaCl₂. PD 12:30 AM 12-30-81. Unable to regain circulation. Plan to drill without returns to approximately 1600' (Glorietta) and run 7" casing.

18. I hereby certify that the infor	7	to the best of my knowledge and belief.	DATE_	1-4-82	
	Williams	OIL AND GAS INSPECTOR		JAN 8	1982

CONDITIONS OF APPROVAL, IF ANYI