

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR  
MESA PETROLEUM CO.
3. ADDRESS OF OPERATOR  
1000 VAUGHN BUILDING/MIDLAND, TEXAS 79701
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 660' FSL & 760' FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) TD, 4 1/2" Casing & Cement

SUBSEQUENT REPORT OF:

- ☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

RECEIVED  
DEC 21 1981

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

5. LEASE NM - 27970	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	7. UNIT AGREEMENT NAME	8. FARM OR LEASE NAME COVOTE FEDERAL	9. WELL NO. 7Y	10. FIELD OR WILDCAT NAME UNDESIGNATED ABO	11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA Sec 5, T7S, R22E	12. COUNTY OR PARISH Chaves	13. STATE New Mexico	14. API NO.	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3869' GR
------------------------	--------------------------------------	------------------------	---	-------------------	---	---	--------------------------------	-------------------------	-------------	---

NOTE: Report results of multiple completion zone (change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Drilled 7 7/8" hole to TD of 4113' on 12-17-81. Ran 97 jts 10 5/8" K-55  
Casing set at 4025'. Cemented with 500 sx "C" + 5# KCL + 2/10% CFR-2. PD at 9:00 PM, 12-17-81. Cement did not circulate  
rig at 6:00 AM, 12-18-81. WOCU estimated to arrive 12-27-81.

XC: USGS (6), TLS, CEN RCDS, ACCTG, MEC, REM , PARTNERS, ROSWELL  
Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

18. I hereby certify that the foregoing is true and correct

SIGNED PETER W. CHESTER TITLE REGULATORY COORDINATOR DATE 12-18-81

ACCEPTED FOR RECORD  
PETER W. CHESTER

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL: DEC 23 1981

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side