

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
2. NAME OF OPERATOR
MESA PETROLEUM CO.
3. ADDRESS OF OPERATOR
1000 VAUGHN BUILDING/MIDLAND, TEXAS 79701
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL & 1980' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Spud, 13 3/8" csg & cement

SUBSEQUENT REPORT OF

- ☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED
JAN - 7 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

5. LEASE
NM-29416
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
MILNER FEDERAL
9. WELL NO.
2
10. FIELD OR WILDCAT NAME
UNDESIGNATED ABO
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SEC 8, T8S, R25E
12. COUNTY OR PARISH
CHAVES
13. STATE
NEW MEXICO
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3638' GR

NOTE: Report results of multiple completion or zone change on Form 9-330.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded well with 17 1/2" hole on 12-15-81. Encountered hole problems to 885'. Able to gain sufficient hole integrity on 12-23-81 to run 12 jts of 13 3/8", 48#, H-40 casing set at 466'. Unable to get lower due to hole caving in. Cemented with 700 sx HLW + 1# Flocele + 4% CaCl, 300 sx Thixset + 4% CaCl, and tailed in with 300 sx "C" + 2% CaCl. PD at 9:00 p.m. 12-23-81. Cement did not circulate. Set four plugs with a total of 900 sx Thixset + 4% CaCl to circulate cement. WOC total of 56 hours. Blew hole dry and waited one hour-no fluid. Reduced hole to 12 1/4" and drilled ahead on 12-27-81.

XC: USGS (6), TLS, CEN RCDS, ACCTG, MEC, REM, PARTNERS, ROSWELL, FILE

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED ROGER A. CHAMMAN TITLE REGULATORY COORDINATOR DATE 12-29-81

(This space for Federal or State office use)

APPROVED BY JAN 1 1 1981 TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO